

APPENDIX A  
 Asbestos Containing Materials Summary  
 Single-Family Residence  
 4330 Beltline Road  
 Irving, Texas

Sample No.	Material	Location (Area)	Friable/ Nonfriable	Assessed Condition*	Estimated Quantity
<b>Single-Family Residence</b>					
1, 2, 3, 4, 5	Ceiling texture/wall texture/ drywall/joint compound (white, crows feet)	Garage	Category II Non-friable	G	1,190 sq. ft.
6, 7, 8, 9, 10, 11, 12	Ceiling texture/wall texture/ drywall/joint compound	Throughout	Category II Non-friable	G	6,256 sq. ft.
13, 14, 15	Drywall/joint compound associate with Wall Covering (red and purple flowers)	Kitchen, Hallway off Kitchen	Category II Non-friable	G	468 sq. ft.
22, 23, 24	Sink Undercoating (white)	Laundry/Utility Room	Category II Non-friable	G	1 sink
31, 32, 33	Sink Undercoating (gray)	Kitchen, Bar	Category II Non-friable	G	2 sinks
43, 44, 45	Drywall/joint compound associated with wall covering (red)	Bathroom #4	Category II Non-friable	G	216 sq. ft.
46, 47, 48	Interior Building Caulk (white) associated with planter box	Foyer planter box	Category II non-friable	G	15 ln. ft.
49, 50, 51	Drywall/joint compound associated with fabric wall covering	Formal Dining Room	Category II Non-friable	G	448 sq. ft.

APPENDIX A  
Asbestos Containing Materials Summary  
Single-Family Residence  
4330 Beltline Road  
Irving, Texas

Sample No.	Material	Location (Area)	Friable/ Nonfriable	Assessed Condition*	Estimated Quantity
<b>Single-Family Residence</b>					
55, 56, 57	Wall texture/drywall/joint compcund (white, semi-smooth)	Foyer	Category II Non-friable	G	480 sq. ft.
58, 59, 60	Drywall, joint compound associated with wall covering (gold and black)	Front Bathroom off foyer	Category II Non-friable	G	240 sq. ft.
64, 65, 66	Drywall/joint compound associated with wall covering (pink with flowers)	Bedroom and bathroom #1	Category II Non-friable	G	360 sq. ft.
67, 68, 69	Drywall/joint compound associated with wall covering (burgundy)	Bedroom and bathroom #2	Category II Non-friable	G	640 sq. ft.
70, 71, 72	Drywall/joint compound associated with wall covering (tan)	Bathroom #3	Category II Non-friable	G	376 sq. ft.
73, 74, 75	Drywall/joint compound associated with wall covering (big flower pattern)	Master Bedroom	Category II Non-friable	G	120 sq. ft.
76, 77, 78	Drywall/joint compcund associated with wall covering (off-white, yellow and blue flowers)	Master Bath	Category II Non-friable	G	156 sq. ft.

APPENDIX A  
Asbestos Containing Materials Summary  
Single-Family Residence  
4330 Beltline Road  
Irving, Texas

Sample No.	Material	Location (Area)	Friable/ Nonfriable	Assessed Condition*	Estimated Quantity
79, 80, 81	Drywall/joint compound associated with wall covering (yellow)	Master Bathroom/ Powder Room	Category II Non-friable	G	80 sq. ft.
91, 92, 93	Mastic associated with marble (brown) countertops	Master Bathroom countertop	Category II non-friable	G	5 sq. ft.

APPENDIX B  
 Identified Homogenous Materials  
 Asbestos Containing Materials Summary  
 Single-Family Residence  
 4330 Beltline Road  
 Irving, Texas

Material	Asbestos Containing	Sample Numbers
<b>Single-Family Residence</b>		
Ceiling texture/wall texture/drywall/joint compound (white, crow's feet)	Yes	1, 2, 3, 4, 5
Ceiling texture/wall texture/drywall, joint compound (crow's feet)	Yes	6, 7, 8, 9, 10, 11, 12
Drywall/joint compound associated with wall covering (red and purple flowers)	Yes	13, 14, 15
12"X12" Floor tile (brown, wood pattern)	No	16, 17, 18
1'X1' Ceiling tile (white, rough with brown mastic)	No	19, 20, 21
Sink undercoating (white)	Yes	22, 23, 24
Ceramic tile grout (gray) associated with ceramic floor tile	No	25, 26, 27
Ceramic tile grout (white) associated with ceramic wall tile	No	28, 29, 30
Sink undercoating (gray)	Yes	31, 32, 33
12"x12" Floor tile (marble pattern)	No	34, 35, 36
1'X1' Ceiling tile (white) with fissures	No	37, 38, 39
Cove base mastic (dark brown) associated with cove base (brown)	No	40, 41, 42
Drywall/joint compound associated with wall covering (red)	Yes	43, 44, 45
Interior building caulk (white) associated with planter box	Yes	46, 47, 48
Drywall/joint compound associated with fabric wall covering	Yes	49, 50, 51
Plaster molding (white)	No	52, 53, 54
Wall texture/drywall/joint compound (white, semi-smooth)	Yes	55, 56, 57
Drywall/joint compound associated with wall covering (gold and black)	Yes	58, 59, 60
Mastic associated with marble (tan)	No	61, 62, 63
Drywall/joint compound associated with wall covering (pink with flowers)	Yes	64, 65, 66

Material	Asbestos Containing	Sample Numbers
<b>Single-Family Residence</b>		
Drywall/joint compound associated with wall covering (burgundy)	Yes	67, 68, 69
Drywall/joint compound associated with wall covering (tan)	Yes	70, 71, 72
Drywall/joint compound associated with wall covering (big flower pattern)	Yes	73, 74, 75
Drywall/joint compound associated with wall covering (off-white, yellow and blue flowers)	Yes	76, 77, 78
Drywall/joint compound associated with wall covering (yellow)	Yes	79, 80, 81
Mirror mastic	No	82, 83, 84
Wire cover	No	85, 86, 87
Black mastic associated with TSI	No	88, 89, 90
Mastic associated with marble (brown) countertops	Yes	91, 92, 93
Ceramic tile grout (white) associated with ceramic wall tile	No	94, 95, 96
Marble floor tile thin set (gray)	No	97, 98, 99
Unfinished drywall associated with attic	No	100, 101, 102
Roof shingles	No	103, 104, 105
Exterior building caulk (white)	No	106, 107, 108
Pool plaster	No	109, 110, 111
Grout (white) associated with pool	No	112, 113, 114
Grout (white) associated with ceramic pool tile	No	115, 116, 117
Exterior building caulk (gray)	No	118, 119, 120
<b>Mobile Home</b>		
Drywall and ceiling texture (white, rough)	No	121, 122, 123
Resilient sheet flooring (over wood)	No	124, 125, 126