

IRVING FIRE DEPARTMENT



INFORMATION RELEASE



EMERGENCY SITUATION

For Immediate Release

Contact: Jason Reid

972-721-2651

Irving Fire Department

Irving, Texas - On 6/24/2020 at 1415 hours, the Irving Fire Department responded to a Hazmat Incident at the intersection of N. MacArthur Blvd. and Northgate. The first emergency personnel were on-scene at 1423 hours. There were 5 pieces of emergency equipment sent to this scene. There were no injuries to civilians and no injuries to first responders.

Additional Comments: Engine 7 responded to investigate the smell of gas in the area, and then upgraded the call to a Hazmat Incident upon discovering a cut 2" gas line at the northeast corner of the intersection. In addition to Engine 7, Truck 8, HAZMAT 8, a Battalion Chief, and an EMS Supervisor responded.